

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-2706	DATE	August 8, 2018
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	A possible non-compliance of the fuel pipes positioning near an aerodynamic shield could generate friction between the pipe and shield, and eventually cause a fuel leak. The operation involves adding a sheath to the fuel pipes, or in some cases, the fuel pipes will need to be replaced.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-P875G01	PEUGEOT 5008	2016, 2017	68
LDA-P87AH01	PEUGEOT 5008	2016, 2017	40
	TOTAL		108