

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	gai-2708	DATE	Aug. 22, 2018
MANUFACTURER	DUCATI MOTOR HOLDING SpA (Japanese Importer : DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	the existing routing from the Airbox and the fuel tank drain hoses is going to be modified in order to avoid the contact against the horizontal exhaust manifold. The official Ducati dealer will reroute both hose. This will be performed free of charge		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-VA01	Supersport	2017-2018	48
2BL-VA01	Supersport S	2017-2018	283
		TOTAL	331