

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	4322	DATE	August 30 ,2018
MANUFACTURER	NIPPON TREX CO., LTD.		
DESCRIPTION OF DEFECT	Due to the strength poverty of aluminum hinge of rear door of cargo box, there is possibility that cracks may occur on the said hinge if the rear door repeatedly open and hold. Therefore, in the worst case, the said hinge will break, and there is possibility that the rear door of cargo box will come off when opening the door.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-MK38L	Condor	2015	1
TKG-MK38L	Condor	2016	1
TKG-MK38C	Condor	2015	1
TKG-MK38C	Condor	2016	1
TKG-MK38C	Condor	2016	1
TKG-MK38C	Condor	2016	2
TKG-MK38C	Condor	2016	2
TKG-MK38C	Condor	2016	1
TKG-MK38C	Condor	2016	1
TKG-MK38C	Condor	2016~2017	2
TKG-MK38C	Condor	2016	1
TKG-MK38C	Condor	2017	1
TKG-MK38C	Condor	2016	1
TKG-MK38C	Condor	2016	2
TKG-MK38C	Condor	2016~2017	2
TKG-MK38C	Condor	2016	2
TKG-MK38C	Condor	2016~2017	5
TKG-MK38C	Condor	2016	3
TKG-MK38C	Condor	2016~2017	2
TKG-MK38C	Condor	2016	4
TKG-MK38C	Condor	2016	2
TKG-MK38C	Condor	2017	1
2PG-BRR90T2	Condor	2017	1
2RG-BRR90T2	Condor	2017	1
TPG-FED9Y	Kazet	2016	1
TKG-FK64F	Fighter	2016~2017	6
TKG-FK61F	Fighter	2016~2017	8
2KG-FK61F	Fighter	2018	2
2KG-FK64F	Fighter	2018	5
2KG-FD2ABG	Ranger	2018	1
2KG-FC2ABA	Ranger	2018	2
2PG-FRR90S2	Forward	2018	1
2PG-FRR90T2	Forward	2018	2
TOTAL			69