

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import Vehicles~~

| | | | |
|-----------------------|---|------|-----------|
| CAMPAIGN No. | Gai-2713 | DATE | 2018/8/31 |
| MANUFACTURE | MASSEY FERGUSON SA (Japanese Importer :MSK Farm Machinery Corporation CEO Zenta Ishikawa) | | |
| DESCRIPTION OF DEFECT | The screw of the differential ring gear may have incorrect tightening torque. Therefore, rotation and vibration of the gear may cause the screw to loose. If the ring gear and the pinion gear have been not engaged, they may be damaged and occurred abnormal noise. In the worst case, the vehicle may become unable to drive. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---------|-----------------|---------------------|-------------------|
| NO TYPE | F933VARIO S4 | 2017 | 1 |
| | F936VARIO S4 | | 3 |
| | F939VARIO S4 | | 2 |
| | | TOTAL | 6 |