

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4315	DATE	August 31. 2018
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	At the valve of agricultural tractor, the structure of the hydraulic throttle valve is improperly, in case of working with the heavy implement attached, excessive pressure is applied to the hydraulic pump. Using in that condition, the oil seal of pump is damage and oil is flowed into the engine. The transmission might result in malfunction and it may be impossible to run in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	「EG765」	2004~2009	228
-	「EG765」	2005~2008	119
-	「EG775」	2004~2009	310
	「EG782」	2004~2009	461
SB-82B	「EG775」	2005~2009	209
	「EG782」	2005~2009	407
-	「EG76」	2009~2010	29
	「EG83」	2009~2010	32
KDP-83B	「EG76」	2009~2010	78
	「EG83」	2009~2010	163
TOTAL			2,036