

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4316	DATE	August 31. 2018
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>At the hydraulic pipe of agricultural tractor,</p> <p>①the shape of the pipe from the hydraulic pump to the work system valve is improperly, the pipe is assembled with high stress. Using in that condition, repeated stress is applied by vibration and the pipe is damaged and oil is leaked. The transmission might result in malfunction and it may be impossible to run in the worst case.</p> <p>②the assembled structure of the pipe from traveling valve to the work system valve is improperly, excessive stress occurs due to clogging of soil and stones near the mounting part. Using in that condition, the pipe is damage and oil is leaked. The transmission might result in malfunction and it may be impossible to run in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	「EG48」	2009～2014	①400
	「EG53」	2009～2014	①836
-	「JD-1530」	2009～2014	①125
-	「EG48Y」	2009～2014	①194 ②127
	「EG53Y」	2009～2014	①767 ②454
KDN-65H	「EG58」	2009～2014	①335
	「EG65」	2009～2014	①525
-	「JD-1630」	2009～2014	①203
KDN-65J	「EG58Y」	2009～2014	①543 ②346
	「EG65Y」	2009～2014	①1,888 ②787
TOTAL			①5,816 ②1,714