

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4325	DATE	Sep. 3. 2018
MANUFACTURER	Kawasaki Heavy Industries, Ltd.		
DESCRIPTION OF DEFECT	On eligible units, Improper welding between center-stand spring mounting pin and left side's center-stand bracket may cause the pin to shift or fall off resulting in the center-stand spring falling off. If the center stand springs falls off the center stand may not remain fully retracted and can drop and touch the ground while riding. This could cause loss of control increasing the risk of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
2BL-ZXT02A	Ninja H2 SX SE	2018	568	
TOTAL			568	