

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4328	DATE	Sep.5.2018
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the hybrid system computer of the subject vehicles, due to improper programming, there is a possibility that, when the accelerator pedal is deeply depressed during highway driving conditions, the computer may not be able to complete a shift control process within a required period of time. If this were to occur, an abnormality will be judged by the computer, warning lights will illuminate, and the hybrid system will shut down, resulting in the loss of motive power.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
DAA-GWZ100	[LC500h]	2016-2018	1,434	
		TOTAL	1,434	