

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 3 1 8	DATE	Sep. 6. 2018
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>On the ball spring to keep key position of ignition switch, due to inappropriate maintenance of forming equipment in spring production process, the uneven shape was printed on surface of the spring.</p> <p>Therefore, the spring could be possible fatigue breakage after using ignition key repeatedly, and if heavier items (e.g. a heavy key chain) are attached to the ignition key, and by the vibration during driving, key position may be turned from the "ON" position to the other position.</p> <p>As the result, vehicle power supply will be stop and engine may be stop.</p> <p>Furthermore, if a crash does occur on this condition, airbag will not operate.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBF-VR2E26	NV 3 5 0 CARAVAN	2 0 1 6 ~ 2 0 1 7	4, 5 0 5
LDF-VW2E26			3, 4 0 5
LDF-VW6E26			2, 2 3 1
LDF-CW8E26			7 2 2
LDF-CW4E26			2 5 2
CBF-CS4E26			1, 2 0 9
CBA-KS2E26			6 3 0
CBF-DS4E26			5 5
LDF-DW4E26			7 4

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES		
DBF-VY12	NV150AD	2016~2017	8,938		
DBF-VZNY12			2,443		
DBA-Y12	WINGROAD	2016~2017	1,371		
DBF-VM20	NV200 VANETTE	2016~2017	5,772		
DBA-M20	NV200 VANETTE NV200	2016~2017	1,055		
CBF-SQ2F24	ATLAS	2016~2017	1,667		
CBF-SQ1F24			278		
PDG-SZ2F24			451		
PDG-SZ5F24			334		
SKG-TZ2F24			110		
TKG-SZ1F24			31		
PKG-SZ4F24			28		
PDG-TZ3F24			42		
DBA-YF15			JUKE	2016~2017	80
DBA-E12			NOTE	2017	557
DBA-TB17	SYLPHY	2016~2017	279		
LDF-JVW2E26	ISUZU COMO	2016~2017	86		
LDF-JVW6E26			64		
CBF-JVR2E26			20		
LDF-JCW4E26			7		
LDF-JCW8E26			6		
CBF-JCS4E26			1		
LDF-JDW4E26			1		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBF-ASQ2F24	ISUZU ELF	2017	16
CBF-ASQ1F24			2
TKG-ASZ2F24			3
TKG-ASZ5F24			2
TKG-ASZ1F24			2
DBF-BVY12	MAZDA FAMILIA VAN	2017	789
DBF-BVZNY12			196
DBF-CVY12	MITSUBISHI LANCER CARGO	2017	314
DBF-CVZNY12			117
DBF-BVM20	MITSUBISHI DELICA VAN	2017~2018	131
DBA-BM20	MITSUBISHI DELICA D:3	2017	56
TKG-BSZ5F24	MITSUBISHI FUSO CANTER	2016~2017	120
TKG-BSZ2F24			73
TKG-BSZ1F24			6
TKG-BSZ4F24			2
TOTAL			38,533

The affected parts shipped as repair parts, but the vehicles installed them cannot be identified.

PARTS NAME	PARTS NO.	DELIVERLY YEAR	QUANTITY	Note
IGN Switch	48750-0M010	2016~2017	743	
Steering Lock Set IGN Key Set	48700-6J388 99810-EU50A 99810-MD01B etc	2016~2017	1,355	
Total			2,098	