VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

 CAMPAIGN No.
 Gai-2716
 DATE
 2018/9/13

 MANUFACTURE
 Daimler AG (Japanese Importer : Mercedes-Benz Japan Co,. Ltd.)
 >

 DESCRIPTION OF DEFECT
 On certain V-Class vehicles (447 platforms) with 4-cylinder diesel engine, a pressure-offset error of the differential pressure sensor might occur. In this case the exhaust after-treatment might be impaired. As a result, this could lead to an exceedance of the emission limit.

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
LDA-447811	V220d	2016	3,319
LDA-447815			463
		TOTAL	3,782