

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2718	DATE	2018/9/13
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	On certain S-Class vehicles (222 platform) two screw nuts, which secure the power bars inside the pre-fuse-box in the trunk, might not have been installed. This could lead to higher resistance between the power bars, increasing the risk of fire. Additionally an intermittence of contact between the power bars could lead to a loss of vehicle functions. The engine operation, the seat belt functions and the instrument cluster could be impaired, increasing the risk of a crash and injuries in case of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-222066	S400	2018	170
DBA-222186	S560 4MATIC		110
DBA-222183C	S560		9
DBA-222183			154
ABA-222176C	S600		3
DBA-222986	Mercedes Maybach S560 4 MATIC		5
ABA-222980C	Mercedes Maybach S650		2
DBA-222983C	Mercedes Maybach S560		8
			TOTAL