

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

| | | | |
|-----------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|--------------|
| CAMPAIGN No. | 4311 | DATE | 19 SEP. 2018 |
| MANUFACTURE | MARUYAMA MFG.CO.,INC | | |
| DESCRIPTION OF DEFECT | In the steering unit of agricultural chemical spraying vehicle, the strength of the knuckle arm is insufficient, the knuckle arm may be damaged due to an impact or the like during running on a bad road, and it may be impossible to turn. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|----------|-------------------|---------------------|-------------------|
| MARUYAMA | SSA- α 605 | 2018 | 29 |
| | SSA-V602 | | |
| | | TOTAL | 29 |