

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	4312	DATE	19 SEP. 2018
MANUFACTURE	MARUYAMA MFG.CO.,INC		
DESCRIPTION OF DEFECT	In a hydraulic control valve of an agricultural chemical spraying vehicle, the structure of the hydraulic hose mounting bracket is inappropriate, hydraulic fluid may leak from the hose mounting part. Therefore, if it continue to be used, in the worst case, due to lack of hydraulic fluid, the transmission may malfunction and it may be impossible to run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
MARUYAMA	SSA- α 605	2018	59
	SSA- α 1005		
	SSA-V602		
	SSA-V1002		
		TOTAL	59