

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4338	DATE	September.27, 2018
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In certain the passenger's airbag inflators, gas generating propellant may get deteriorated through repetition of environmental temperature and humidity fluctuations. This can, in the event of the airbag deployment, cause abnormal rise in internal pressure of the inflator whereby the container of inflator could be broken.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GB3	「FREED」 「FREED SPIKE」	2014~2015	33,312
DBA-GB4			4,347
DAA-GP3			33,291
DBA-GG7	「FIT SHUTTLE」	2014	1,961
DBA-GG8			886
DAA-GP2		2014~2015	12,166
DAA-ZE2	「INSIGHT」	2014	465
DAA-ZE3	「INSIGHT EXCLUSIVE」		129
ZAA-ZA2	「FIT EV」		10
		TOTAL	86,567