

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~(~~ Import Vehicles )

CAMPAIGN No.	Gai-2723	DATE	2018/9/13
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	On certain GL/GLE/GLS (166 platform) and GLE Coupe (292 platform) vehicles rear brake calipers might have been manufactured outside specifications. Hydrogen might have been embedded in the brake piston material. The embedded hydrogen could diffuse into the hydraulics of the rear brake circuit, leading to compressibility in the system. This could impair the brake performance of the rear axle and lead to an elongated brake pedal travel. In driving situations with necessary ESP brake actuation at the rear axle, this actuation might not have the full effectivity regarding the stabilization of the vehicle. In this case the vehicle controllability might not be supported as intended. This could increase the risk of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-166874	GL63 4MATIC	2018	2
LDA-166024	GLE350d 4MATIC		1
	GLE350d 4MATIC Coupe		1
CBA-166064	Mercedes AMG GLE43 4MATIC Coupe		1
CBA-166074	Mercedes AMG GLE63S 4MATIC Coupe		1
LDA-166824	GLS350d 4MATIC		3
		TOTAL	9