

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

RECALL No.	Gai-2728	DATE	Oct. 5. 2018
MANUFACTURER	Ford Motor Company (Japanese Importer: Ford Japan Limited)		
DESCRIPTION OF DEFECT	<p>Models Affected: Certain Kuga 2012-2014 MY vehicles built in Valencia (Spain) plant produced from 12th July 2013 through 19th June 2014.</p> <p>Concern Description: In the event of an impact which deploys the front seat belt retractor pre-tensioner, there is a possibility that the insulation material on the inner face of the lower 'B' pillar trim could be subjected to a concentrated heat source that could ignite the insulation material, resulting in fire.</p> <p>SERVICE ACTION: Dealers are required to shorten the length of 'B' pillar trim insulation material by 180mm. Refer to the Recommended Rework Procedure for detailed instructions.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR FIELD SERVICE ACTION	NUMBER OF VEHICLE
ABA-WFOJTM	Ford Kuga	2013-2014	1,263 units
		TOTAL	1,263 units