

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4337	DATE	Oct, 05, 2018
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	Due to lack of insulation performance of radio antenna wire harness terminal, it may contact with the CEU when terminal disconnected, posing a risk of fire.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
M7131	M7131	2015~2016	15
M7151	M7151	2015~2016	39
M7171	M7171	2015~2016	45
YDR-M7001	M7-131	2016~2017	41
	M7-151	2016~2017	116
	M7-171	2016~2017	77
-	M7-171	2016~2017	20
		TOTAL	353