

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	4346	DATE	Oct. 15. 2018
MANUFACTURER	NIPPON FRUEHAUF COMPANY LIMITED		
DESCRIPTION OF DEFECT	There is something lacking in grease filling to wheel bearing because the work when producing, is improper in a driving gear of a semitrailer. Therefore when wheel bearing discolors by lack of a lubrication, and the use is continued in the state which is just as it is, wheel bearing has seizure, the worst occasion, fire or wheel disengage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DFPDF342CN	Semi Trailer	2018	2
DFPDG341A (Modified)	Van Semi Trailer	2018	3
DFPDX331A	Semi Trailer	2017	1
DFPDX341M	Semi Trailer	2017	2
DFPFH341A (Modified)	Semi Trailer	2017-2018	10
	Tank Semi Trailer	2017	20
	Dump Semi Trailer	2017	2
DFPFX338C	Tank Semi Trailer	2018	16
DFPFX340K	Semi Trailer	2017	1
DFPFX343A	Semi Trailer	2017	2
DFPTF341A	Van Semi Trailer	2017	1
DFPTF341A (Modified)	Van Semi Trailer	2017-2018	41
	Tank Semi Trailer	2018	1
	Refrigerated Van Semi Trailer	2017-2018	10
DFWFX341B	Van Semi Trailer	2018	1
KFKDH320S	Container Semi Trailer	2017-2018	5
KFKDH320SN	Container Semi Trailer	2018	1
KFKDJ320 (Modified)	Container Semi Trailer	2018	2
KFKDX330A	Container Semi Trailer	2017	2
KFKEH340	Container Semi Trailer	2017	2
KFKGG340S	Container Semi Trailer	2017-2018	7
KFKGG340SN	Container Semi Trailer	2017-2018	6
KFKGG340SN (Modified)	Container Semi Trailer	2017	1
KFKGG340W (Modified)	Container Semi Trailer	2017-2018	5
KFKHH240 (Modified)	Container Semi Trailer	2018	2
KFKHX340M	Container Semi Trailer	2017	4
RFVFX341F	Refrigerated Van Semi Trailer	2017	5
RFVFX341G	Refrigerated Van Semi Trailer	2017	2
RFVFX341K	Refrigerated Van Semi Trailer	2017	1
		Total	158

[Note] In the range of the chassis number of vehicle recall, may have vehicles that do not qualify are also included.