

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2471	DATE	October 19 <sup>th</sup> , 2018
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The battery-positive cable links the battery with the power distribution box which supplies electric power to the vehicle. Due to inappropriate metal coating material and configuration of the connector of the battery-positive cable, corrosion may occur by vehicle vibration and contact resistance may increase. This results in insufficient electric power supply from the power distribution box to the vehicle electrical components. In worst case, engine may stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-VL18	「BMW X1 sDrive 18i」	2011	914
ABA-VL25	「BMW X1 xDrive 25i」	2011	294
ABA-VA40	「BMW M3 Sedan」	2007 - 2009	670
ABA-WD40	「BMW M3 Coupe」	2007 - 2009	6
		TOTAL	2,195