

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2727	Date	Oct 24, 2018
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In the engine starting device, since the length of the earth cable mounted to the vehicle body is inappropriate, there is a case where the earth cable connecting position on the engine side is broken due to vehicle body vibration during running. As the result, the starter circuit is shut off and the engine does not start.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-16CZD	VW The Beetle 1.2/77kW	2012-2015	19,837
DBA-16CBZ	VW The Beetle Cabriolet 1.2	2013-2015	1,108
		Total	20,945