

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4353	DATE	Oct. 25. 2018
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	<p>On certain leaf-air combined suspensions of heavy duty tractors, due to the improper material of the stopper for the leaf, when the leaf and the stopper contact in time of driving over a bump etc., the stopper may not be able to absorb the load fully, adding too much load on the shaft for fixing the stopper. Therefore, the shaft concerned may fatigue and crack while in operation, resulting the stopper and the shaft to drop and obstruct the traffic.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDG-SS1EKAG LKG-SS1EKAG QDG-SS1EKAG QKG-SS1EKAG	[HINO Profia]	2011~2014	218
QPG-SS1EKDG		2014~2018	197
		TOTAL	415