

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2744	DATE	Nov.1.2018
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the front passenger airbag inflator of the subject vehicles, due to insufficient protection against moisture absorption into the propellant, there is a possibility that the propellant could degrade after several years of exposure to temperature and moisture fluctuations. In this condition, the inflator may rupture in the event the airbag is activated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UA-ZZE136	[VOLTZ]	2002	73
TA-ZZE137			43
UA-ZZE138			37
		TOTAL	153