

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4363	DATE	Nov.1.2018
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the airbag control module, due to insufficient consideration of influence of electrical noise, some module could have insufficient insulation against electrical noise. In this condition, the IC chip in the module could become damaged due to electrical noise generated by operation of electrical equipment. In the worst case, the airbag(s) could deploy while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UA-NCP81G CBA-NCP81G DBA-NCP81G	[SIENTA]	2003-2015	7,658
UA-NCP85G CBA-NCP85G DBA-NCP85G		2003-2014	968
UA-ANE10G CBA-ANE10G DBA-ANE10G	[WISH]	2003-2009	686
UA-ANE11W CBA-ANE11W DBA-ANE11W			843
UA-ZNE10G CBA-ZNE10G DBA-ZNE10G			2,692
UA-ZNE14G CBA-ZNE14G			747
CBA-ANM10G DBA-ANM10G CBA-ANM10W DBA-ANM10W	[Isis]	2004-2009	2,039

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-ANM15G DBA-ANM15G CBA-ANM15W DBA-ANM15W	[Isis]	2004-2009	846
CBA-ZNM10G CBA-ZNM10W			451
CBA-NZE120	[COROLLA]	2004-2006	8
CBA-NZE121 DBA-NZE121	[COROLLA] [COROLLA RUNX]		487
CBA-NZE124	[ALLEX]		118
CBA-ZZE122			251
CBA-ZZE124			84
TA-ZZE123	[COROLLA RUNX] [ALLEX]		55
CBA-NZE121G DBA-NZE121G	[COROLLA FIELDER]		216
CBA-NZE124G			44
TA-ZZE122G CBA-ZZE122G			142
TA-ZZE123G			35
CBA-ZZE124G		62	
UA-NZE121N CBA-NZE121N	[COROLLA SPACiO]	2003-2007	84
UA-ZZE122N CBA-ZZE122N			100
UA-ZZE124N CBA-ZZE124N			47
UA-NCP60 CBA-NCP60 DBA-NCP60	[ist]		265

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UA-NCP61 CBA-NCP61	[ist]	2003-2007	364
UA-NCP65 CBA-NCP65			241
UA-AZT250 CBA-AZT250	[AVENSIS]	2003-2006	7,309
CBA-AZT251		2005-2006	921
UA-AZT255 CBA-AZT255		2003-2006	1,290
UA-AZT250W CBA-AZT250W	[AVENSIS WAGON]	2003-2006	5,001
CBA-AZT251W		2005-2006	785
UA-AZT255W CBA-AZT255W		2003-2006	1,163
		TOTAL	36,002