

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4354	DATE	November 9 .2018
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>①In the air intake hose to the turbocharger of agricultural tractor, the mounting structure is inappropriate, the hose may come off due to vibration. Therefore, if you continue to use it as it is, the output of the engine drops, and in the worst case the running speed may not come out.</p> <p>②In the oil cooler hose of the agricultural tractor, the shape of the hose is inappropriate and cracks may occur in the hose. And cracks develop due to engine vibration, oil leakage occurs, and in the worst case, the transmission may malfunction and it may be impossible to run.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
—	「YT463」	2015~2017	496	②496
	「YT470」	2015~2017	817	②817
—	「YT490」	2015~2015	22	①22 ②22
		2015~2017	876	①591 ②876
	「YT5101」	2015~2017	117	①85 ②117
	「YT5113」	2015~2015	28	①28 ②28
		2015~2017	785	①529 ②785
	「YT5113」	2015~2017	150	①150
		TOTAL	3,291	①1,405 ②3,141