

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4355	DATE	November 9 .2018
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	In the link bolt at hydrostatic transmissions of agricultural tractors, the instruction to manufacture is improperly. It is loosened due to thermal influence during painting and drying in the manufacturing process. Therefore, looseness proceeds due to vibration of the engine and even if the main shift lever is neutralized, it moves at a very small speed, or the bolt come off and the shift does not be possible.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	「YT222」	2016~2017	499
	「YT225」	2016~2017	2,047
		2016~2017	244
-	「YT228」	2016~2017	599
	「YT232」	2016~2017	513
		2016~2017	90
TOTAL			3,992