

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4356	DATE	November 9 .2018
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	In the wheel of the agricultural tractor, since the accuracy of the rim bolt is inappropriate, even if tightened with the specified torque, the axial force is insufficient and the rim bolt loosen. Therefore, the rim bolt and the nut fall off due to vibrations and in the worst case, there is a possibility that the tire falls out and the running becomes impossible.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	「EG83」	2011～2013	5
KPD-83B	「EG83」	2010～2014	67
EDR-105B	「EG97」	2011～2014	6
		2011～2012	34
	「EG105」	2011～2013	43
		2011～2013	155
TOTAL			310