

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4359	DATE	Oct. 13, 2018
MANUFACTURER	TOYOTA CUSTOMIZING&DEVELOPMENT CO., Ltd.		
DESCRIPTION OF DEFECT	In the aluminum wheel mounted as the frame parts, since the design size of the wheel center part is inappropriate, the wheel nut may loosen as the use continues. Therefore, abnormal noise occurs, and in the worst case, the wheel may drop off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDF-GDH201V	「HIACE」	2017-2018	66
QDF-GDH206V		2017-2018	81
CBF-TRH200V		2010-2018	67
		TOTAL	214