

**VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN**

Domestic Vehicles

<b>CAMPAIGN No.</b>	<b>4370</b>	<b>DATE</b>	<b>Nov 13, 2018</b>
<b>MANUFACTURER</b>	<b>SUZUKI MOTOR CORPORATION</b>		
<b>DESCRIPTION OF DEFECT</b>	Due to the improper assembling process, the passenger air bag mount screw may be missing in some vehicle. If the screw is missing, the air bag may fail to deploy in the correct manner resulting in the insufficient protecting for the passenger.		

<b>TYPE</b>	<b>COMMERCIAL NAME</b>	<b>MODEL YEAR RECALLED</b>	<b>NUMBER OF VEHICLES</b>
DBA-MA26S	SOLIO	2018	42
DAA-MA36S			514
DAA-MA46S			53
DAA-MN71S	XBEE		382
DAA-FF21S	IGNIS		45
DAA-MB36S	DELICA D:2		138
DAA-MB46S			19
		<b>TOTAL</b>	<b>1,193</b>