

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4366	DATE	November 15,2018
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	<p>① On certain gasoline engine vehicles with idling stop functions, due to inappropriate programming of idling stop control, an idling stop may be engaged even if the battery has deteriorated. If this occurs, the engine may not re-start after the vehicle is stopped at a traffic light, etc. with an idling stop engaged.</p> <p>② On the engine ECUs of certain vehicles with idling stop functions, due to inappropriate programming of engine control, catalyst deterioration diagnosis may not work appropriately. As a result, the warning light may not turn on even if the catalyst has deteriorated.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-A05A	「MIRAGE」	2012～2015	32,240
DBA-A03A		2014～2018	12,564
DBA-GA4W	「RVR」	2011～2017	15,932
DBA-GF7W	「OUTLANDER」	2012～2017	3,391
DBA-GF8W		2012～2017	10,918
DBA-CV2W	「DELICA」	2011～2017	11,982
DBA-CX6A	「GALANT」	2011～2015	1,351
DBA-CY6A		2011～2015	3,664
		TOTAL	92,042