

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2754	DATE	Nov. 27 <sup>th</sup> , 2018
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	<p>The fault involves the Exhaust Gas Recirculation (EGR) Module of diesel engine. Part of this module is the EGR cooler, where coolant can become leaky due to insufficient durability of this component. The leaking coolant could create in combination with soot in the EGR module which may consequently become an ignitable deposits through exposure to high exhaust gas temperature, resulting in melting of the intake manifold and a consequent to loss of engine power, lighting of engine check lamp and thermal incident as a worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-1S20	BMW 118d	2016 - 2017	5,054
LDA-2C20	BMW 218d ActiveTourer	2015 - 2017	5,714
LDA-2E20	BMW 218d GranTourer	2015 - 2017	4,761
LDA-3D20	BMW 320d	2013 - 2016	3,241
LDA-8C20		2016 - 2017	2,326
LDA-8T20	BMW 320d Gran Turismo	2017	35
LDA-FW20	BMW 523d	2013 - 2016	1,418
LDA-JC20		2016- 2017	1,254
LDA-MX20	BMW 523d Touring	2013 - 2016	561
LDA-JM20		2017	241
LDA-HT20	BMW X1 xDrive 18d	2016 - 2017	2,804
LDA-WY20	BMW X3 xDrive 20d	2014 - 2017	3,432
LDA-KS30	BMW X5 xDrive 35d	2014 - 2017	1,367
LDA-KS30S		2015 - 2017	225
LDA-XN15	MINI Cooper D	2016 - 2017	1,450
LDA-XN20	MINI Cooper SD	2016 - 2017	1,043
LDA-XT15	MINI Cooper D 5 Door	2016 - 2017	2,450
LDA-XT20	MINI Cooper SD 5 Door	2016 - 2017	927
LDA-LR20	MINI Cooper D Clubman	2016 - 2017	2,208
	MINI Cooper SD Clubman	2016 - 2017	1,403
LDA-XD20F	MINI Cooper D Crossover	2014 - 2016	3,958
LDA-XD20A	MINI Cooper D Crossover A4	2014 - 2016	1,867
LDA-ZB20	MINI Cooper SD Crossover	2014 - 2016	2,975

LDA-YT20	MINI Cooper D Crossover	2016 - 2017	1,240
	MINI Cooper D Crossover A4	2016 - 2017	455
	MINI Cooper SD Crossover A4	2016 - 2017	710
LDA-RS20	MINI Cooper D Paceman	2014 - 2016	199
		TOTAL	53,318