

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4377	DATE	November 29 ,2018
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In the exhaust gas diffusing prevention devices of the heavy-duty trucks, some connector portions of the urea hoses might melt from the heat of the DPD (Diesel Particulate Defusers) because the hoses' heat resistance is insufficient. Therefore, if the drivers keep driving the trucks without repair, urea might leak out, and this may result in failing to comply with the emissions standards.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-CVR60C	[GIGA]	2017-2018	34
2KG-CVR77C 2PG-CVR77C		2017	2
2KG-CXE60C		2018	3
2PG-CXE77C		2017-2018	28
2KG-CXG60CT		2018	1
2KG-CXG77C 2PG-CXG77C		2017-2018	12
2KG-CXM60CT		2017-2018	21
2KG-CXM77C 2PG-CXM77C		2018	3
2KG-CXY77CJ 2PG-CXY77CJ		2017-2018	43
2KG-CXZ60CT		2017-2018	133
2KG-CXZ77CT 2PG-CXZ77CT		2017-2018	1,522
2KG-CYE60CM		2017-2018	90
2PG-CYE77CZ		2017-2018	11
2KG-CYG60CM		2017-2018	160
2KG-CYH77C 2PG-CYH77C		2017-2018	141

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2KG-CYJ77C 2KG-CYJ77CA 2PG-CYJ77C 2PG-CYJ77CA	[GIGA]	2017-2018	4,582	
2PG-CYJ77CL		2017-2018	7	
2DG-CYJ77CW		2018	4	
2KG-CYJ77CZ 2PG-CYJ77CZ		2017-2018	38	
2KG-CYL60C		2017-2018	19	
2KG-CYL77C 2KG-CYL77CA 2PG-CYL77C 2PG-CYL77CA		2017-2018	1,518	
2KG-CYL77CM 2PG-CYL77CM		2017-2018	128	
2KG-CYL77CZ 2PG-CYL77CZ		2017-2018	66	
2KG-CYM77C 2PG-CYM77C		2017-2018	117	
2KG-CYM77CM 2PG-CYM77CM		2017-2018	129	
2KG-CYM77CZ 2PG-CYM77CZ		2018	2	
2KG-CYY60CY		2017-2018	2	
2KG-CYY77C 2PG-CYY77C		2017-2018	129	
2KG-CYY77CJ 2PG-CYY77CJ		2017-2018	39	
2KG-CYY77CY 2PG-CYY77CY		2017-2018	253	
2KG-CYZ77C 2PG-CYZ77C		2017-2018	237	
2KG-CYZ77CJ 2PG-CYZ77CJ		2017-2018	61	
2KG-CYZ77CM 2PG-CYZ77CM		2017-2018	358	
			TOTAL	9,893