

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4379	DATE	Nov.29 2018
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	Regarding the exhaust pipe of the engine for the crane chassis, found that an improper sealing agent might have been applied to the joint of the pipes. Therefore, it couldn't keep sufficient flexibility and could have a crack due to vibration so on, then, it may cause to leakage of the exhaust gas and urea water at worst.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
KA6360	—	2017~2018	7	
TOTAL			7	