

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicle

CAMPAIGN No.	4385	DATE	Nov.30, 2018
MANUFACTURER	KOBELCO CONSTRUCTION MACHINERY CO.,LTD		
DESCRIPTION OF DEFECT	<p>There are some wrong installations of coupling which are made by Silicon rubber and used for power transmission, due to improper instruction for installation of parts.</p> <p>At the worst case, the coupling may be worn out due to uneven load applied and got damaged. Then machine may not be able to propel</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CM03	MK650	2014-2016	4units
CM03L	MK650	2014-2015	4units
TOTAL			8