

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	gai-2761	DATE	Dec. 10, 2018
MANUFACTURER	DUCATI MOTOR HOLDING SpA (Japanese Importer : DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	<p>Some of the rear wheel pads are unsuitable for quality control, and some of the bonds between the friction material of the brake and the base plate are insufficient in strength. Therefore, during use, the friction material of the brake pad peels off and falls, and in the worst case, the rear wheel brake may not work.</p> <p>Check the production lot number of the rear wheel pad. The official Ducati dealer will replace the brake pad. This will be performed free of charge</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-HA01	959Panigale	2018	2
2BL-VA01	1299Panigale R Final Edition	2018	25
		TOTAL	27