

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import Vehicles~~

CAMPAIGN No.	Gai-2757	DATE	2018/12/11
MANUFACTURE	MASSEY FERGUSON SA (Japanese Importer :MSK Farm Machinery Corporation CEO Zenta Ishikawa)		
DESCRIPTION OF DEFECT	In the crankshaft of the agricultural tractor, some of the surface finish of the crankshaft is rough because the surface finishing process is inappropriate. Therefore, if you continue to use it as it is, there is a danger that the connecting rod and the bearing will wear out and abnormal noise will be generated from the engine.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
WDR-SU49A	MF6614-4D	2016	2
	MF6615-4D		2
	MF6616-4D		1
WDR-SU49A2	MF6614-4V		1
	MF6616-4V		1
		TOTAL	7