

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import Vehicles~~

CAMPAIGN No.	Gai-2758	DATE	2018/12/11
MANUFACTURE	MASSEY FERGUSON SA (Japanese Importer :MSK Farm Machinery Corporation CEO Zenta Ishikawa)		
DESCRIPTION OF DEFECT	<p>① Due to the inadequate size design of the valve pipe that sends hydraulic oil to the trailer, some durability against hydraulic pressure is insufficient. Therefore, the pipe cracks. In the worst case, hydraulic oil may leak and the hydraulic device may become inoperative.</p> <p>② Due to the inadequate size design of pack pipes that send hydraulic fluid to the front device, there is a case that the durability against oil pressure is insufficient. Therefore, the pipe cracks. In the worst case, hydraulic oil may leak and the hydraulic device may become inoperative.</p> <p>③ Due to insufficient thickness of the resonator of the hydraulic device, durability against oil pressure is insufficient. Therefore, the resonator is cracked. In the worst case, hydraulic oil may leak and the hydraulic device may become inoperative.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-SU66A	MF7720-4D	2016~2017	9 (①9②7③7)
YDS-SU74A	MF7724-4D		4 (①4②4③2)
	MF7726-4D		7 (①7②7③6)
		TOTAL	20 (①20②18③15)