

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4399	DATE	Dec.13 2018
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In some medium-duty trucks with rear air suspension, since the installation method of the lateral rod was inappropriate, the tightening torque of the mounting bolts may be insufficient. Therefore, the mounting bolts can loosen. In the worst case, the lateral rod may come off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FK65FY	「FUSO FIGHTER」	2018~2018	2
2KG-FK65FZ		2018~2018	10
		TOTAL	12