VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2760	DATE	December 14, 2018		
MANUFACTURER	General Motors LLC				
DESCRIPTION OF DEFECT	Affected vehicles may not comply with Safety Regulations for Road Vehicles - Article 22-5 "Child restraint anchorage system". During the vehicle assembly process, small amounts of excess structural adhesive may have been applied to vehicle's inboard child-seat anchorage bars, and hardened adhesive may cause interference of the bars and child seat latches when installed. Inboard Child Seat anchorage bars will be inspected for adhesive, and the adhesive will be removed and an anti-corrosion primer will be applied to the bar.				

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
ABA-O1SL	Cadillac CT6	2016-2018		172
			TOTAL	172