## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Import Vehicles

CAMPAIGN No.	GAI-2765	DATE	December, 2018	
MANUFACTURER	Automobili Lamborghini SpA			
	(Japanese Importer: Audi Japan KK)			
DESCRIPTION OF DEFECT	Under extreme conditions of usage of the vehicle the wheel centering bushes drive			
	pegs (bolts centering and supporting the brake discs to the wheel's hub) may			
	become loose. The wheel system however is secured by the central lock. Extreme			
	conditions of driving, vibrations and severe usage stress factors over time may			
	cause the drive pegs to come loose in the VIN range affected. With loose drive pegs			
	and heavy condition of use for a long time, may lead to an overstress of the wheel			
	locking system with risk of its fracture.			

ТҮРЕ	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
ABA-47L539	Aventador LP750-4	2015	2