

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2767	DATE	December 19 <sup>th</sup> , 2018
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	The fault involves the plug connection from the wiring harness, which supplies power to the blower controller for the air conditioner. Due to inappropriate material of the plug connection coating, this may deteriorate due to friction corrosion caused by high current flow and vehicle vibration. This can lead to overheating of the plug connection and subsequently to melting. In very rare cases, this can lead to a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-3K20	B3 Biturbo	2007-2010	143
	B3 Biturbo Coupe	2007-2009	52
ABA-3K2H	B3 Biturbo Cabrio	2008-2009	29
	B3 Biturbo Touring	2008-2009	13
	B3 Biturbo Touring 4WD	2009	4
ABA-3K30	B3S Biturbo	2010-2011	69
	B3S Biturbo Touring	2010-2011	18
	B3S Biturbo Touring 4WD	2010	4
	B3S Biturbo Coupe	2010-2011	15
	B3S Biturbo Cabrio	2010-2011	13
ADC-3N1A	D3 Biturbo	2009-2010	87
	D3 Biturbo Touring	2009-2010	42
ADC-3N1M	D3 Biturbo	2009-2010	39
	D3 Biturbo Coupe	2009-2010	12
		TOTAL	540