

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

<b>CAMPAIGN No.</b>	<b>4407</b>	<b>DATE</b>	<b>Dec 25, 2018</b>
<b>MANUFACTURER</b>	Hino Motors,Ltd. FURUKAWA UNIC CORPORATION		
<b>DESCRIPTION OF DEFECT</b>	With fuel tank breather pipe for car carrier, the internal dimensions of the breather pipe become long because of production instructions were inappropriate. As a result, may leak fuel from the breather hose, if fuel supplied to the full edge of the filler.		

<b>TYPE</b>	<b>COMMERCIAL NAME</b>	<b>MODEL YEAR RECALLED</b>	<b>NUMBER OF VEHICLE</b>
2KG-XZU720M	HINO DUTRO	2018	12
2KG-XZU720	TOYOTA DYNA	2018	9
<b>TOTAL</b>			<b>21</b>