

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	外-2771	DATE	10. Jan. 2019
MANUFACTURE	Tesla Motors Inc. (Japanese Importer : Tesla Motors Japan G.K )		
DESCRIPTION OF DEFECT	Tesla has determined that a defect may exist in certain MY 2014 – 2016 Tesla Model S vehicles equipped with Takata non-desiccated ammonium nitrate inflators in frontal passenger air bag systems. Over time, moisture intrusion could cause the inflator to rupture when the passenger's frontal air bag deploys in a crash. If the inflator ruptures, metal fragments could strike vehicle occupants, potentially resulting in serious injury or death.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-SL1S	Model S	2014~2015	115
ZAA-SL1SA		2014~2015	144
ZAA-SL1S2		2014	21
ZAA-SL1S2A		2014~2015	158
ZAA-SL2S		2015	21
ZAA-SL2SA		2015	35
ZAA-SL2S2		2015	7
ZAA-SL2S2A		2015	75
ZAA-SWL1S		2015~2016	14

ZAA-SWL1SA		2015～2016	17
ZAA-SWL2S		2015～2016	33
ZAA-SWL2SA		2015～2016	52
ZAA-SWL2S2		2015～2016	8
ZAA-SWL2S2A		2015～2016	42
不明		2016	234
		TOTAL	976

