

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4404	DATE	January 10. 2019
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>In the reverser bracket of the agricultural tractor, since the strength standard is inappropriate, cracks may be generated in the weld if an external force is applied to the lever guide. Therefore, the bracket may be damaged, and it may be impossible to perform the shift operation normally.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
—	「YT333」	2016~2018	150	
		TOTAL	150	