

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4405	DATE	January 10. 2019
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	In the bracket of the reverser lever of the agricultural tractor, the strength of the bracket is insufficient because the shape is inappropriate. As a result, the bracket is damaged by repetitive operation of the lever, and the lever can not be supported. In the worst case, even if the lever is operated, there is a possibility that it is impossible to shift forward and backward.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	「YT219」	2017	1
	「YT221」	2017	1
-	「YT222」	2016~2017	611
	「YT225」	2016~2017	786
-	「YT228」	2016~2017	156
	「YT232」	2016~2017	81
TOTAL			1,636