

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4412	DATE	January 15, 2019
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	The exhaust pipe of the diesel engine may lack durability because of improper design. Accordingly, if the engine is used as it is, its exhaust pipe resonates with engine vibration and may crack, and exhaust gas leaks in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
WDP-WA124	「WA100-7」	2013 - 2017	3840
WDP-M285	「FH60」 「FH70」 「FH80」	2016-2017	26
YDN-M286	「FH35」 「FH40」 「FH45」 「FH50」	2015-2018	105
YDN-M288	「FH60」 「FH70」 「FH80」	2018	8
		TOTAL	3979