

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4414	DATE	Jan.16.2019
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the front passenger airbag inflator of the subject vehicles, due to insufficient protection against moisture absorption into the propellant, there is a possibility that the propellant could degrade after several years of exposure to temperature and moisture fluctuations. In this condition, the inflator may rupture in the event the airbag is activated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBE-NCP51V	[PROBOX] [SUCCEED]	2014	14,001
DBE-NCP55V			7,564
DBE-NCP50V	[PROBOX]		6,643
QFE-NCP52V			19
DBA-NZE151N	[COROLLA RUMION]	2014-2015	3,505
DBA-ZRE152N			1,199
DBA-ZRE154N			855
DBA-GSE20	[IS250C]	2014	136
DBA-GSE21	[IS350C]		39
DBA-USE20	[IS F]		61
		TOTAL	34,022