

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4416	DATE	Jan. 16. 2018
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	In the front passenger airbag inflator of the subject light duty trucks, due to insufficient protection against moisture absorption into the propellant, there is a possibility that the propellant could degrade after several years of exposure to temperature and moisture fluctuations. In this condition, the inflator may rupture in the event the airbag is activated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
NBG-BZU600M	[HINO Dutro]	2015	3
ABG-TRC600M ABG-TRC600X		2014~2015	6
TQG-XKC605M TSG-XKC605M		2014~2016	5
TQG-XKU600M TQG-XKU600X TSG-XKU600X		2014~2016	7
TQG-XKU605M TSG-XKU605M		2014~2016	5
TQG-XKU700M TSG-XKU700M		2014~2016	63
TQG-XKU710M TSG-XKU710M		2014~2016	9
TQG-XKU720M TSG-XKU720M		2015~2016	10
TKG-XZC600M		2014~2015	2
TKG-XZC605M TKG-XZC605Y		2014~2016	297
TKG-XZC610T		2014~2016	13
TKG-XZC630T		2016	1
TKG-XZC645M		2014~2016	13
TKG-XZC655M		2014~2016	11
TKG-XZC675M TKG-XZC675T		2014~2016	21
TKG-XZC710M		2014~2016	22

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
TKG-XZU600E TKG-XZU600F TKG-XZU600M TKG-XZU600X	[HINO Dutro]	2014~2016	219	
TKG-XZU605M		2014~2016	219	
TKG-XZU610T		2014~2016	19	
TKG-XZU620T		2014~2016	34	
TKG-XZU630T		2014~2016	10	
TKG-XZU640F TKG-XZU640M		2014~2016	82	
TKG-XZU645M		2014~2016	42	
TKG-XZU650F TKG-XZU650M		2014~2016	8	
TKG-XZU655M		2014~2016	44	
TKG-XZU675M TKG-XZU675T		2014~2016	136	
TKG-XZU685M		2014~2016	159	
TKG-XZU695M		2014~2016	149	
TKG-XZU700M TKG-XZU700X		2014~2016	108	
TDG-XZU710M TKG-XZU710M		2014~2016	147	
TDG-XZU720M TKG-XZU720M		2014~2016	145	
TDG-XZU730M TKG-XZU730M		2014~2016	15	
TKG-XZU775M		2014~2016	20	
NBG-BZU600 NBG-BZU600A		[Toyota Dyna 200] [Toyota Dyna 300]	2014~2017	14
ABG-TRC600 ABG-TRC600A		[Toyota Dyna 400] [Toyota Toyoace G25]	2014~2016	24
ABG-TRU600		[Toyota Toyoace G35]	2014~2015	3
TQG-XKC605 TSG-XKC605	[Toyota Toyoace G45]	2014~2016	50	
TQG-XKU600 TSG-XKU600		2014~2015	2	
TQG-XKU605 TSG-XKU605		2014~2016	30	
TSG-XKU640		2015	1	
TSG-XKU650		2015~2016	24	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TSG-XKU655	[Toyota Dyna 200]	2016	1
TQG-XKU700	[Toyota Dyna 300]	2014~2016	32
TSG-XKU700	[Toyota Dyna 400]		
TQG-XKU710	[Toyota Toyoace G25]	2014~2016	8
TSG-XKU710	[Toyota Toyoace G35]		
TQG-XKU720	[Toyota Toyoace G45]	2014	1
TKG-XZC600		2014~2017	13
TKG-XZC605		2014~2017	650
TKG-XZC605V			
TKG-XZC610D		2014~2016	54
TKG-XZC630D		2014~2015	2
TKG-XZC645		2014~2016	29
TKG-XZC655		2014~2016	28
TKG-XZC675		2014~2016	82
TKG-XZC675D			
TKG-XZC710		2014~2016	25
TKG-XZU600		2014~2016	70
TKG-XZU600A			
TKG-XZU600D			
TKG-XZU600H			
TKG-XZU600W			
TKG-XZU605		2014~2017	483
TKG-XZU610D		2014~2016	21
TKG-XZU620D		2014~2016	72
TKG-XZU630D		2014~2016	5
TKG-XZU640		2014~2016	32
TKG-XZU640W			
TKG-XZU645		2014~2017	62
TKG-XZU650		2014~2016	19
TKG-XZU655		2014~2016	88
TKG-XZU675		2014~2016	80
TKG-XZU675D			
TKG-XZU685		2014~2016	74
TKG-XZU695		2014~2016	43
TKG-XZU700		2014~2016	37
TKG-XZU700A			
TDG-XZU710		2014~2017	379
TKG-XZU710			
TDG-XZU720		2014~2017	259
TKG-XZU720			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TDG-XZU730	[Toyota Dyna 200]	2014~2016	24
TKG-XZU730	[Toyota Dyna 300]		
TKG-XZU775	[Toyota Dyna 400] [Toyota Toyoace G25] [Toyota Toyoace G35] [Toyota Toyoace G45]	2014~2016	108
		TOTAL	4,973

Vehicles which had the affected parts installed after they rolled off the assembly line.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS
TKG-XZC605M	[HINO Dutro]	2017	1	
		TOTAL	1	

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS	REMARKS
AIR BAG ASSY	73970-37021	2014~2015	8	
		TOTAL	8	