VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2770	DATE	Jan. 17, 2019	
MANUFACTURER		Audi (Japanese Importer: Audi Japan KK) The bolts securing the passenger airbag module to the dash panel may not have been tightened to the correct torque. The bolts securing the passenger airbag module to the dash panel must be checked on the affected vehicles and replaced if necessary.		
DESCRIPTION OF DEFECT	The bolts securing the passenger tightened to the correct torque. The bolts securing the passenger			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8WCYRA	A4 Allroad	2018	1
ABA-F5CWGL	S5 SB	2018	1
DBA-F5CVKL	A5 SB 2.0T	2017	1
DBA-F5CYRL	A5 SB 2.0Tq	2018	2
		Total	5