

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2774	DATE	January 22 nd , 2019
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	The fault involves the Exhaust Gas Recirculation (EGR) Module of diesel engine. Part of this module is the EGR cooler, where coolant can become leaky due to insufficient durability of this component. The leaking coolant could create in combination with soot in the EGR module which may consequently become an ignitable deposits through exposure to high exhaust gas temperature, resulting in melting of the intake manifold and a consequent to loss of engine power, lighting of engine check lamp and thermal incident as a worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
FDA-3P10	D3 Biturbo	2014-2016	105
	D3 Biturbo Touring	2014-2015	33
	D4 Biturbo Coupe	2014-2015	30
FDA-PP10	XD3 Biturbo	2015	27
FDA-MP20	D5 Turbo	2013-2015	263
		TOTAL	458