CHILD RESTRAINT SYSTEM SAFETY RECALL CAMPAING IN JAPAN

			omestic / Import Items		
CAMPAING No.	S o u - 1 2	DATE	28-Jan-2019		
MANUFACTURER	CARMATE MFG. CO., LTD.				
DESCRIPTION OF DEFECT	The shape of the shoulder belt hole of the child seat and the operation structure of the shoulder belt hanger are inappropriate. When adjusting the length of the shoulder belt, pulling out only one side belt strongly may cause a loop portion of the shoulder belt to bend. Therefore, if the operation is repeatedly performed, in the worst case, the shoulder belt may come off the shoulder belt hanger and the occupant may not be sufficiently restrained.				

COMMERCIAL NAME	ТҮРЕ	CLASSIFICATION	MODEL YEAR RECALLED	NUMBER OF ITEMS
Ailebebe PAPATTO Grance CF520 CF521 CF522 CF523 CF524	E43-44R- 040015	Groups I / II / III	(2018. 3. 5~	5,022pcs.
				5,022pcs.

Domestic Import Item